

CERTIFICATE OF COMPLIANCE

Certificate Number R15431
Report Reference R15431-20190403
Issue Date 2020-JUNE-25

Issued to: HILTI CONSTRUCTION CHEMICALS, DIV OF HILTI INC
7250 Dallas Pky, Legacy Tower Suite 1000
Plano TX 75024

**This certificate confirms that
representative samples of**

FIRESTOP DEVICES
CFS-CID MD P 2”/4”, 3”/4” and 4”/4”
CFS-CID MD M 2”/4”, 3”/4” and 4”/4”
CFS-CID MD P 2”/2.5”, 3”/2.5” and 4”/2.5”
CFS-CID MD M 2”/2.5”, 3”/2.5” and 4”/2.5”
CFS-CID MD PX 2”/4”, 3”/4” and 4”/4”
CFS-CID MD PX 2”/2.5”, 3”/2.5” and 4”/2.5”

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: ANSI/UL 1479, Fire Tests of Penetration Firestops
CAN/ULC S115, Standard Method of Fire Tests of Firestop Systems

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

