

CERTIFICATE OF COMPLIANCE

Certificate Number 20130131-R15431
Report Reference R15431-20130129
Issue Date 2013-JANUARY-31

Issued to: HILTI CONSTRUCTION CHEMICALS, DIV OF HILTI INC
5400 S 122ND EAST AVE
TULSA OK 74146

This is to certify that
representative samples of

FIRESTOP DEVICES
USC, CNC Firestop device designated CFS-CC 4"
Firestop Cable Collar for use in specific through-penetration
firestop systems.

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 1479 - Fire Tests of Through-Penetration Firestops
CAN/ULC-S115 - Standard Method of Fire Tests of Firestop
Systems

Additional Information:

See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Classification Mark for the U.S. and Canada should be considered as being covered by UL's Classification and Follow-Up Service and meeting the appropriate U.S. and Canadian requirements.

The UL Classification Mark includes: the UL in a circle symbol:  with the word "CLASSIFIED" (as shown); a control number (may be alphanumeric) assigned by UL; a statement to indicate the extent of UL's evaluation of the product; and the product category name (product identity) as indicated in the appropriate UL Directory. The UL Classification Mark for Canada includes: the UL Classification Mark for Canada:  with the word "CLASSIFIED" (as shown); a control number (may be alphanumeric) assigned by UL; a statement to indicate the extent of UL's evaluation of the product; and the product category name (product identity) in English, French, or English/French as indicated in the appropriate UL Directory.

Look for the UL Classification Mark on the product.



William R. Carney, Director, North American Certification Programs

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at www.ul.com/contactus



CERTIFICATE OF COMPLIANCE

Certificate Number 20130131-R15431
Report Reference R15431-20130129
Issue Date 2013-JANUARY-31



William R. Carney, Director, North American Certification Programs

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at www.ul.com/contactus

