
UL/cUL SYSTEM NO. WW-S-0042

FIRE-RATED JOINT THROUGH CONCRETE WALL ASSEMBLY

ASSEMBLY RATING = 2-HR. L-RATING AT AMBIENT = LESS THAN 1 CFM / LIN FT L-RATING AT 400° F = LESS THAN 1 CFM / LIN FT

FRONT VIEW

SECTION A-A



- 1. CONCRETE WALL ASSEMBLY (2-HR. FIRE-RATING):
 - A. LIGHTWEIGHT OR NORMAL WEIGHT CONCRETE WALL (MINIMUM 4" THICK).
 - B. ANY UL/cUL CLASSIFIED CONCRETE BLOCK WALL.
- 2. MINIMUM 3" THICKNESS MINERAL WOOL SAFING (MIN. 4 PCF DENSITY) TIGHTLY PACKED.
- $oxed{3}$. MINIMUM 1/2" DEPTH OF ANY OF THE FOLLOWING FIRESTOP SEALANTS APPLIED TO EXTERIOR OF WALL : A. 790 OR 795 SEALANT MANUFACTURED BY DOW SILICONES CORP.
 - B. PENSIL 300 SEALANT MANUFACTURED BY GENERAL ELECTRIC SILICONE PRODUCTS DIVISION.
 - C. DYNATROL II CAULK, OR 864 SILICONE CAULK MANUFACTURED BY PECORA CORP.
- 4. MINIMUM 1/2" DEPTH HILTI CP 606 FLEXIBLE FIRESTOP SEALANT OR HILTI CFS-S SIL GG FIRESTOP SILICONE SEALANT APPLIED TO INTERIOR OF WALL.

NOTE: MAXIMUM WIDTH OF JOINT = 1".



HILTI, Inc. Plano, Texas USA (800) 879-8000

Sheet	1 of 1
Scale	1/4" = 1"
Date	Jan. 18, 2019

Drawing No. **WWS** 0042d

Saving Lives through Innovation and Education